PRECISION
ENVIRONMENTAL SERVICES INC.

19431 Sarkis Drive
Mokena, IL 60448
(708) 625-4488
www.precisionenviroservices.com

Radon Test Report

November 23, 2022
Batch #: 112322-2

Customer:
Mr. Jones
xxx Apple St
Mokena IL 60448

Test Site:
Mr. Jones
xxx Apple St
Mokena IL 60448

Rad Elec Recon Continuous Radon Monitors and E-PERM® Electret Ion Chambers were used for radon screening measurements that were conducted at the above referenced test site by: Precision Environmental Services (Cert.#RNI 2018209)

The Results are as follows:

Serial No.	Type	Location	Test Start Date		Test End Date		Results (pCi/L)
293	CRM	Basement	21-Nov-2022	1:30 PM	23-Nov-2022	3:49 PM	4.4

CRM Calibration Due: 08-Aug-2023

Average Radon Concentration in: Basement **4.4 pCi/L**

SMO169	SST	Crawl-Space	21-Nov-2022	1:30 PM	23-Nov-2022	3:50 PM	3.1
SMO309	SST	Crawl-Space	21-Nov-2022	1:30 PM	23-Nov-2022	3:50 PM	3.0

Average Radon Concentration in: Crawl-Space **3.1 pCi/L**

Deployed By: Kris Weigal #RNI2018209
Retrieved By: Kris Weigal #RNI2018209
Analyzed By: Kris Weigal #RNI2018209 **Reader S/N:** E1345 **Reader Calibration Due:** 14-Jun-2023

Conditions: Requirements for Closed-Building Met
Tampering: None Observed
Weather: No Abnormal Weather Conditions
Vents: Not Applicable / Fan Not Applicable
Mitigation: No System Installed

Radon Health Risk Information

Radon is the second leading cause of lung cancer after smoking. The U.S. Environmental Protection Agency (EPA) and the Surgeon General strongly recommend that further action be taken when a home's radon test results are 4.0 pCi/L or greater and to also consider future radon retesting or mitigation for test results 2.0 to 3.9 pCi/L. The national average indoor radon level is about 1.3 pCi/L. The higher the home's radon level, the greater the health risk to you and your family. Reducing your radon levels can be done easily, effectively and fairly inexpensively. Even homes with very high radon levels can be reduced below 4.0 pCi/L. Please refer to the EPA web site at www.epa.gov/radon for further information to assist you in evaluating your test results or deciding if further action is needed.

There is an uncertainty with any measurement result due to statistical variations and other factors such as daily and seasonal variations in radon concentrations. Variations may be due to changes in weather, operation of the dwelling or possible interference with the necessary test conditions.

Signature: Kristine Weigal **Date:** 23-Nov-2022

PRECISION
ENVIRONMENTAL SERVICES INC.

19431 Sarkis Drive
Mokena, IL 60448
(708) 625-4488
www.precisionenviroservices.com

Radon Test Report

November 23, 2022
Batch #: 112322-2

Customer:
Mr Jones
Mokena IL 60448

Test Site:
Mr Jones
Mokena IL 60448

Graphical Results for: Rad Elec Recon 293





PRECISION
ENVIRONMENTAL SERVICES INC.

19431 Sarkis Drive
Mokena, IL 60448
(708) 625-4488
www.precisionenviroservices.com

Radon Test Report

November 23, 2022
Batch #: 112322-2

Customer:
Mr. Jones
Mokena IL 60448

Test Site:
Mr. Jones
Mokena IL 60448

Hourly Detailed Report for: Rad Elec Recon 293

Record #	Date/Time	pCi/L	Fahrenheit (°F)	Pressure (inHg)	Humidity (%)	Tilts
1	21-Nov-2022 15:30	1.9	66	29.4	37	0
2	21-Nov-2022 16:30	3.9	65	29.4	37	0
3	21-Nov-2022 17:30	5.8	65	29.4	37	0
4	21-Nov-2022 18:30	4.5	65	29.4	37	0
5	21-Nov-2022 19:30	4.5	66	29.5	37	0
6	21-Nov-2022 20:30	5.1	65	29.5	37	0
7	21-Nov-2022 21:30	5.3	65	29.5	37	0
8	21-Nov-2022 22:30	4.9	65	29.5	37	0
9	21-Nov-2022 23:30	4.9	65	29.5	37	0
10	22-Nov-2022 0:30	4.3	65	29.5	37	0
11	22-Nov-2022 1:30	5.3	65	29.5	36	0
12	22-Nov-2022 2:30	5.4	65	29.5	36	0
13	22-Nov-2022 3:30	5.1	65	29.5	36	0
14	22-Nov-2022 4:30	5.5	66	29.5	36	0
15	22-Nov-2022 5:30	5.0	66	29.5	36	0
16	22-Nov-2022 6:30	4.0	66	29.5	36	0
17	22-Nov-2022 7:30	4.0	67	29.5	36	0
18	22-Nov-2022 8:30	5.7	67	29.5	36	0
19	22-Nov-2022 9:30	5.0	67	29.5	35	0
20	22-Nov-2022 10:30	4.1	66	29.5	35	0
21	22-Nov-2022 11:30	2.8	66	29.5	36	0
22	22-Nov-2022 12:30	3.9	66	29.5	36	0
23	22-Nov-2022 13:30	4.4	66	29.4	36	0
24	22-Nov-2022 14:30	2.8	66	29.4	36	0
25	22-Nov-2022 15:30	4.6	66	29.4	36	0
26	22-Nov-2022 16:30	5.9	65	29.4	37	0
27	22-Nov-2022 17:30	5.9	65	29.4	37	0
28	22-Nov-2022 18:30	4.1	65	29.4	37	0
29	22-Nov-2022 19:30	4.7	65	29.4	37	0
30	22-Nov-2022 20:30	4.0	65	29.4	37	0
31	22-Nov-2022 21:30	4.9	64	29.4	37	0
32	22-Nov-2022 22:30	5.3	64	29.4	37	0
33	22-Nov-2022 23:30	3.2	64	29.4	37	0
34	23-Nov-2022 0:30	3.7	64	29.4	37	0
35	23-Nov-2022 1:30	4.8	65	29.4	37	0
36	23-Nov-2022 2:30	5.1	65	29.4	37	0
37	23-Nov-2022 3:30	3.8	65	29.4	37	0
38	23-Nov-2022 4:30	2.5	66	29.4	37	0
39	23-Nov-2022 5:30	5.0	66	29.4	37	0
40	23-Nov-2022 6:30	3.6	66	29.4	37	0
41	23-Nov-2022 7:30	3.5	66	29.4	37	0

PRECISION
ENVIRONMENTAL SERVICES INC.

19431 Sarkis Drive
Mokena, IL 60448
(708) 625-4488
www.precisionenviroservices.com

Radon Test Report

November 23, 2022
Batch #: 112322-2

Customer:
Mr. Jones
Mokena IL 60448

Test Site:
Mr. Jones
Mokena IL 60448

Record #	Date/Time	pCi/L	Fahrenheit (°F)	Pressure (inHg)	Humidity (%)	Tilts
42	23-Nov-2022 8:30	4.9	66	29.4	37	0
43	23-Nov-2022 9:30	3.5	67	29.4	37	0
44	23-Nov-2022 10:30	3.6	66	29.4	37	0
45	23-Nov-2022 11:30	5.5	65	29.4	37	0
46	23-Nov-2022 12:30	3.3	65	29.4	38	0
47	23-Nov-2022 13:30	4.5	65	29.4	38	0
48	23-Nov-2022 14:30	3.8	65	29.4	38	0
49	23-Nov-2022 15:30	4.0	65	29.4	38	0
50	23-Nov-2022 16:30	4.7	65	29.4	38	0